

FIG. 1




FIG. 2




FIG. 3

0993863 - 099404




FIG. 4




FIG. 5

D9933863 • D9933864




FIG. 6

0963853-002601




FIG. 7

09953863 · 092601




FIG. 8




FIG. 9




FIG. 10



FIG. 11




FIG. 12




FIG. 13



FIG. 14




FIG. 15




FIG. 16



FIG. 17




FIG. 18




FIG. 19



FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26

09953863, 0995601

T05260° E98E9660

13 / 18

FIG. 27
PRESSURE DROP THROUGH DISPENSE LINE






FIG. 28

09963863 . 092601




FIG. 29




FIG. 30




FIG. 31




FIG. 32

FIG. 33




FIG. 34




FIG. 35





FIG. 36



09963863 - 092601

18 / 18

